



IDAHO TRANSPORTATION DEPARTMENT

Division of Aeronautics
3483 Rickenbacker Street • Boise ID 83705

(208) 334-8775
itd.idaho.gov/aero

August 23, 2022

Jared Mitton, Manager
Oakley Municipal Airport
P O Box 266
Oakley, ID 83346

SUBJECT: 2022 5010-1 Airport Inspection conducted Mar 18, 2022.
(004277.5*A Oakley Oakley Municipal Airport)

Dear Jared,

Runway: The gravel runway surface continues to be in good condition – it is still very level and with no concerning deformities, undulations, or vegetation growth. Grasses on the edges are growing a bit and would be prudent to spray those edges and keep the growth from advancing toward the center of the runway. Early spraying would help in keeping the growth to a minimum and prevent future work.

Taxiway/Ramp/Tiedowns: The small ramp and tie down area near the hangars I found to be in good condition, overall. Of the 8 potential parking spots that I counted, none had tie down chains available.

Windsock/Standard: I found two windsocks at this facility. The one at rwy end 17 I found to be in good condition with no fading, rips or tears. The metal standard was still leaning to the North just as it was 3 yrs ago. The midfield windsock on the west side was in poor shape. It was all shredded up and half of it was gone. The metal standard was in good working order & had good silver paint. Neither windsock had a segmented circle present.

Miscellaneous/Services: I saw no other major issues or concerns that need/require immediate attention. If you have any questions, please feel free to contact me at: 208-334-8895. Have a great day.

Sincerely,

Florian Ghighina

Flo Ghighina
Airport Inspector/Obstructions Evaluator
