



**IDAHO TRANSPORTATION DEPARTMENT**

Division of Aeronautics  
3483 Rickenbacker St. • Boise ID 83705

(208) 334-8775  
[itd.idaho.gov/aero](http://itd.idaho.gov/aero)

---

10 December, 2020

Loel Fenwick, Manager  
Tanglefoot Seaplane Base  
100 Waterbird Landing  
Coolin, Id 83821

Subject: 2020 5010-1 Airport Inspection conducted September 24, 2020.  
(04165.\*C Coolin Tanglefoot SPB)

Hi Loel,

On September 24, 2020, I visited the airport to conduct the FAA 5010-1 Airport Safety Data Inspection. These inspections are performed under contract with the FAA on a three-year cycle. The completed process updates the Airport Master Record (FAA Form 5010) and several connected publications. I have summarized the inspection findings below:

At the time of the inspection your Sea Plane facility was in good condition with ample mooring space. The docs appeared to be in good condition and with plenty of space to park several airplanes if needed. I did not see a windsock on the premises at that time, however, you did have a nice US flag flying at the entrance toward the hangar.

I saw no other significant changes or safety concerns with this airfield. If you have any questions or if need any assistance, please feel free to call me at 208-334-8895. Have a great day.

Sincerely,

*Florian Ghighina*

Flo Ghighina  
Airport Inspector/Obstructions Evaluator  
Division of Aeronautics

---