



IDAHO TRANSPORTATION DEPARTMENT

Division of Aeronautics
1390 W Gowen Road • Boise ID 83705

(208) 334-8775
itd.idaho.gov/aero

January 5, 2021

Brent Webster – Owner/ Manager
W.E. Ranch LLC
908 Francis Circle
Kaysville, UT 84037

Subject: 2020 5010-1 Airport Inspection conducted October 7, 2020.
(04269.*A Thatcher W.E. Airport)

Hello Brent,

On October 7, 2020, I visited the airport to conduct the FAA 5010-1 Airport Safety Data Inspection. These inspections are performed under contract with the FAA on a three-year cycle. The completed process updates the Airport Master Record (FAA Form 5010) and several connected publications. I have summarized the inspection findings below:

Runway: 17-35

Overall, the sandy/gravel runway surface was in good condition with just minor undulations present closer to the rwy ends. Rwy had no lights, was free of vegetation, and had wide open and clear approaches to both rwy ends – that is the advantage of being located on top of a bluff surrounded by down sloping terrain.

Taxiway & Ramp/Tie Downs:

There is no taxiway at this facility. North end of the airfield has a small turnaround area to the E that could be used for parking aircraft – at best, one could fit 2-3 airplanes in there. No tie-down chains were present.

Windsock/Standard/Segmented Circle:

There was one small windsock at this airfield located on the N end of the rwy and behind the small shed located in the turnaround area. Windsock was in good shape and displayed good and bright orange color. No segmented circle at this airfield. In the future, re-location of the windsock on the west side of the airfield – directly across from where it is now, would allow it to do a better job showing wind condition as it would be totally in the open and unhindered by the shed nearby.

Miscellaneous/Services: Overall, this airport is well maintained for what it is and well taken care of. I saw no other significant changes or safety concerns with this airfield. If you have any questions or if I can be of any assistance to you, please feel free to call me directly at 208-334-8895 or via email: flo.ghighina@itd.idaho.gov. Have a great day.

Sincerely,

Flo Ghighina

Florian Ghighina
Airport Inspector/Obstructions Evaluator
Idaho Division of Aeronautics
208-334-8895