

**Key No. 23117 - SH-33 Canyon Creek Bridge Repair  
Madison County**

Item No	Description	QTY	Unit
201-010A	CLEARING & GRUBBING	1.00	LS
203-015A	REM OF BITUMINOUS SURF	350.00	SY
203-080A	REM OF GUARDRAIL/BARRIER	330.00	FT
205-040A	GRANULAR BORROW	750.00	CY
212-011A	FIBER WATTLE	120.00	FT
212-020A	SILT FENCE	261.00	FT
212-070A	GABION Sack	144.00	CY
212-075A	REVEGETATION MAT	13.00	CY
212-095A	INLET PROTECTION	2.00	EACH
212-105A	WATER POLLUTION AND EROSION CONTROL	5,000.00	CA
213-005A	TOPSOIL	74.00	CY
303-021A	3/4" AGGR TY A FOR BASE	447.00	TON
405-435A	SUPERPAVE HMA PAV INCL ASPH&ADD CL SP-3	107.00	TON
605-065A	36" STORM SEWER PIPE	294.00	FT
605-630A	INLET TY 8	2.00	EACH
612-005D	W-BEAM GUARDRAIL	330.00	FT
612-115B	GUARDRAIL TERMINAL, FLARED	1.00	EACH
612-115C	GUARDRAIL TERMINAL, TANGENT	1.00	EACH
621-001A	SEED	0.11	ACRE
621-005A	SEED BED PREPARATION	0.11	ACRE
621-010A	SEEDING	0.11	ACRE
621-020A	MULCH ANCHORING (MECHANICAL)	0.11	ACRE
621-075A	ROLLED EROSION CONTROL PRODUCTS	140.00	SY
624-005A	LOOSE RIPRAP	543.00	CY
626-010A	TEMPORARY TRAFFIC CONTROL SIGNS	274.00	SF
626-050A	DRUMS	20.00	EACH
626-105A	TRAF CNTL MAINTENANCE	20.00	HR
626-116A	TEMP CONCRETE BARRIER	120.00	FT
626-117A	R&R TEMP CONCRETE BARRIER	120.00	FT
626-120A	FLAGGER CONTROL	400.00	HR
630-025A	LONGITUDINAL PAV MKG- WATERBORNE	600.00	FT
640-010A	RIPRAP/EROSION CONT GEOTEXTILE TYPE II	334.00	SY
675-005A	SURVEY	1.00	LS
675-010A	DIRECTED SURVEYING OFFICE COMPUTATIONS	5,000.00	CA
S900-50A	CONTINGENCY AMOUNT DIRECTED REPAIRS	50,000.00	CA
S904-05A	SP ENERGY DISSIPATOR	1.00	LS
S911-05A	SP 36" STORM SEWER PIPE	143.00	FT
S911-05B	SP GROUTED HOLLOW INJECTION ANCHOR	2,250.00	FT
Z629-05A	MOBILIZATION	1.00	LS