



Idaho Division of Aeronautics

5010 AIRPORT INSPECTION FORM



SLOPE RATIO CALCs: D=200/HT (PAVED) ** D/HT (UNPAVED) ** H=D/S ** D=SxHT ** HT=height D=Dist S=Slope

Ratings: Excellent = E Good = G Fair = F Poor = P Failed = FD

Airport: CAMAS CO/FARRFIELD LocID: U86 Paved Undeveloped NPIAS: Y (N) INSP Date: 30 APR 21

Rwy 1: 8-26 Pub Dims: 2950' Lx 40' W G-Earth Dims: Lx W FAA Dims: Lx W Actual Dims: 3000' Lx 45' W Measured: (Y) N w/VEHICLE Δ ME Rwy Markings: N/A Rwy Lights: Y (N) Veg Ctrl: GOOD SFC Type: DIRT SFC Cond: GOOD Rwy End: 8 Lat N: 43° 20' 30.76" Long W: 114° 48' 13.61" Elev 1 GPS: 5059' Elev 2 WCP: 5061' ± 5 Hdg 1: 078°/258° Hdg 2: 078°/258° Ctlg Obstn: (Y) N Description: 19' @ 0', 100' L Close-in Obstn: Y (N) Description: Rwy End: 26 Lat N: 43° 20' 30.61" Long W: 114° 47' 33.64" Elev 1 GPS: 5060' ± 6 Elev 2 WCP: 5058' Hdg 1: 259°/079° Hdg 2: 258°/078° Ctlg Obstn: (Y) (X) Description: 40' PWR. POLE @ 230', 95' R Close-in Obstn: Y (N) Description: Remarks: THERE APPEARS TO BE VEHICULAR TRAFFIC ON THE RWY. LEVELING THOSE TRUCKS OUT W/SOME KIND OF A TOW-BEHIND RAKE OR LEVELING SCREEN WOULD HELP SMOOTHEN THE RWY SFC. OVERALL, THE FACILITY IS IN GOOD SHAPE FOR WHAT IT IS.

Rwy 2: - Pub Dims: Lx W G-Earth Dims: Lx W FAA Dims: Lx W Actual Dims: Lx W Measured: Y N Rwy Markings: Rwy Lights: Y N Veg Ctrl: SFC Type: SFC Cond: Rwy End: Lat N: Long W: Elev 1 GPS: Elev 2 WCP: Hdg 1: Hdg 2: Ctlg Obstn: Y N Description: Close-in Obstn: Y N Description: Rwy End: Lat N: Long W: Elev 1 GPS: Elev 2 WCP: Hdg 1: Hdg 2: Ctlg Obstn: Y N Description: Close-in Obstn: Y N Description: Remarks: N/A

Taxiway: Y N Sfc Type: Sfc Cond: Markings: Y N Signs: Y N Cond: Lights: Y N Reflectors: Y N Both Cond: Veg Ctrl: Remarks: N/A

Ramp/TieDown Area Sfc Type: DIRT Sfc Cond: GOOD # of Spots: 5 # w/Chains/TDs: 4 Markings: Y (N) Lights: N/A Signs: Y (N) Veg Ctrl: GOOD Remarks:

Windsock(s) # of WS on AFLD: 1 WS1 Cond: FAIR Lights: Y (N) Loc: WS2 Cond: Lights: Y N Loc: WS3 Cond: Lights: Y N Loc: Std 1 Type: METAL Cond: GOOD Painted: (Y) N Color WHITE Seg Cr: (Y) N Type: PAINTED ROCKS TP: (Y) N Std 2 Type: Cond: Painted: Y N Color Seg Cr: Y N Type: TP: Y N Std 3 Type: Cond: Painted: Y N Color Seg Cr: Y N Type: TP: Y N Remarks: SEG CR IS OF NON-STD. SIZE - A BIT DIFFICULT TO SEE FM AIR LEFT 2 x NEW WINDSOCKS w/ WINSTON.

Boundary Markers Cond: Veg Ctrl: Type: Metal Wood Rocks Other Painted: Y N Remarks: N/A

Misc/Other Rot BCN: Y N Type: HT: Cond: Working: Y N ??? Veg: Unverif Unable to Verif Veg Ctrl: Signs: Y N Remarks: N/A