



Idaho Division of Aeronautics



5010 AIRPORT INSPECTION FORM/REPORT

SLOPE RATIO CALCs: D=200/HT (PAVED) \*\* D/HT (UNPAVED) \*\* H=D/S \*\* D=SxHT \*\* HT=height D=Dist S=Slope Ratings: Excellent=E Good=G Fair=F Poor=P Failed=FD

Airport: PARMA LocID: 505 (Paved) Undevelopd NPIAS: Y (N) INSP Date: 18 MAR 21

Rwy 1: 12-30 Pub Dims: 2700' L x 50' W G-Earth Dims: L x W FAA Dims: L x W Actual Dims: 2700' L x 50' W Measured: (Y) N VEH DME

Rwy Markings: #s+CL Rwy Lights: (Y) N Veg Ctrl: GOOD

SFC Type: ASPHALT SFC Cond: GOOD

Rwy End: 12 Lat N: 43° 46' 48.90" Long W: 116° 56' 24.89" Elev 1 GPS: 2226' Elev 2 WCP: 2228' ± 13'

Hdg 1: 118°/298° Hdg 2: 119°/299°

Ctlg Obstn: (Y) N Description: 80' TREE @ 530', 150' R

Close-in Obstn: Y (N) Description: —

Rwy End: 30 Lat N: 43° 46' 30.35" Long W: 116° 55' 58.75" Elev 1 GPS: 2223' Elev 2 WCP: 2225' ± 6'

Hdg 1: 300/120° Hdg 2: 299°/119°

Ctlg Obstn: (Y) N Description: 3' BARB WIRE FENCE @ 200', 105' L

Close-in Obstn: (Y) N Description: 3' BW FENCE

Remarks: BMs = Boundary Markers // CL= Center line // RWY LIGHTS ARE NEW, SOLAR FIXTURES & CTAF ACTIVATED. OVERALL, AIRPORT IS IN FAIRLY GOOD CONDITION W/SOME VISIBLE, OLD CRACKS THAT HAVE BEEN PREVIOUSLY TREATED. SLURRY FILL HOLDS GOOD. UNABLE TO VERIFY RWY LIGHTS W/HANDHELD RADIO.

Rwy 2: Pub Dims: L x W G-Earth Dims: L x W FAA Dims: L x W

Actual Dims: L x W Measured: Y N

Rwy Markings: Rwy Lights: Y N Veg Ctrl:

SFC Type: SFC Cond:

Rwy End: Lat N: Long W: Elev 1 GPS: Elev 2 WCP:

Hdg 1: Hdg 2:

Ctlg Obstn: Y N Description:

Close-in Obstn: Y N Description:

Rwy End: Lat N: Long W: Elev 1 GPS: Elev 2 WCP:

Hdg 1: Hdg 2:

Ctlg Obstn: Y N Description:

Close-in Obstn: Y N Description:

Remarks: d fd

Taxiway: Y N Sfc Type: ASPHALT Sfc Cond: EXC. Markings: Y N Signs: Y (N) Cond: —

Lights: Y (N) Reflectors: Y (N) Both Cond: — Veg Ctrl: GOOD

Remarks:

Ramp/TieDown Area Sfc Type: ASPHALT Sfc Cond: GOOD # of Spots: 9 # w/Chains/TDs: 4

Markings: (Y) N Lights: N/A Signs: Y (N) Veg Ctrl: GOOD

Remarks:

Windsock(s) # of WS on AFLD: 1

WS1 Cond: GOOD Lights: Y N Loc:

WS2 Cond: Lights: Y N Loc:

WS3 Cond: Lights: Y N Loc:

Std 1 Type: Cond: Painted: Y N Color Seg Cr: Y N Type: TP: Y N

Std 2 Type: Cond: Painted: Y N Color Seg Cr: Y N Type: TP: Y N

Std 3 Type: Cond: Painted: Y N Color Seg Cr: Y N Type: TP: Y N

Remarks:

Boundary Markers Cond: Veg Ctrl:

Type: Metal Wood Rocks Other N/A

Painted: Y N

Remarks:

Misc/Other Rot BCN: Y (N) Type: HT:

Cond: Working: Y N ? Verif Unverif Verif N/A

Veg Ctrl: Signs: Y N

Remarks: 2 x NEW LG HARBARS ARE UNDER CONSTRUCTION.