



Idaho Division of Aeronautics



5010 AIRPORT INSPECTION FORM/REPORT

SLOPE RATIO CALCS: D=200/HT (PAVED) ** D/HT (UNPAVED) ** H=D/S ** D=SxHT ** HT=height D=Dist S=Slope Ratings: Excellent=E Good=G Fair=F Poor=P Failed=FD

Airport: SLATE CREEK LocID: 157 Paved (Undeveloped) NPIAS: Y (N) INSP Date: 11 AUG 22

Rwy 1: 12-30 Pub Dims: 2600' L x 165' W G-Earth Dims: L x W FAA Dims: L x W Actual Dims: 2670' L x 160' W Measured: (Y) N VEH. DME. Rwy Markings: BMS Rwy Lights: Y (N) Veg Ctrl: F-8 SFC Type: TURF SFC Cond: FAIR Rwy End: 12 Lat N: 45° 40' 27.57" Long W: 116° 18' 34.02" Elev 1 GPS: 1663' ± 5' Elev 2 WCP: — Hdg 1: 120°/300° Hdg 2: 121°/301° Ctlg Obstr: (Y) N Description: 35' PWR. LINE @ 0', 105' L Close-in Obstr: Y (N) Description: — Rwy End: 30 Lat N: 45° 40' 9.44" Long W: 116° 18' 7.45" Elev 1 GPS: 1644' ± 5' Elev 2 WCP: — Hdg 1: 299°/119° Hdg 2: 300°/120° Ctlg Obstr: (Y) N Description: 35' PWR. LINE @ 0', 105' R Close-in Obstr: Y (N) Description: —

Remarks: BMS = Boundary Markers // CL= Center line // RWY SFC COND. IS IN FAIR SHAPE DUE TO 15"-20" TALL GRASS - NEEDS MOWING. GND. ROLL TEST INDICATES MILD TO MODERATE BOUNCING @ 65-70 MPH.

Rwy 2: Pub Dims: L x W G-Earth Dims: L x W FAA Dims: L x W Actual Dims: L x W Measured: Y N Rwy Markings: Rwy Lights: Y N Veg Ctrl: SFC Type: SFC Cond: Rwy End: Lat N: Long W: Elev 1 GPS: Elev 2 WCP: Hdg 1: Hdg 2: Ctlg Obstr: Y N Description: Close-in Obstr: Y N Description: Rwy End: Lat N: Long W: Elev 1 GPS: Elev 2 WCP: Hdg 1: Hdg 2: Ctlg Obstr: Y N Description: Close-in Obstr: Y N Description: Remarks: d fd

Taxiway: Y N Sfc Type: Sfc Cond: Markings: Y N Signs: Y N Cond: Lights: Y N Reflectors: Y N Both Cond: Veg Ctrl: Remarks:

Ramp/TieDown Area Sfc Type: TURF Sfc Cond: FAIR # of Spots: 3 # w/Chains/TDs: 3 Markings: (Y) N Lights: N/A Signs: (Y) N Veg Ctrl: POOR Remarks: PARKING AREA IS COVERED IN 15"-20" TALL GRASS & NEEDS MOWING; AREA IS MARKED BY ORANGE CONES.

Windsock(s) # of WS on AFLD: 1 WS1 Cond: GOOD Lights: Y (N) Loc: LEFT OR RWY END 12. WS2 Cond: Lights: Y N Loc: WS3 Cond: Lights: Y N Loc: Std 1 Type: METAL Cond: GOOD Painted: (Y) N Color: WHITE/ORG Seg Cr: (Y) N Type: ROCKS TP: Y (N) Std 2 Type: Cond: Painted: Y N Color: Seg Cr: Y N Type: TP: Y N Std 3 Type: Cond: Painted: Y N Color: Seg Cr: Y N Type: TP: Y N Remarks: GOOD VEG. CONTROL IN & AROUND THE SEG. CIRCLE.

Boundary Markers Cond: GOOD Veg Ctrl: GOOD Type: Metal Wood (Rocks) Other Painted: (Y) N 70-80% PAINT LEFT - WILL NEED NEW PAINT IN ~ 2 YRS.

Misc/Other Rot BCN: Y N Type: HT: Cond: Working: Y N Verif Unverif Verif N/A Veg Ctrl: Signs: Y N N/A Remarks:

Slate Creek - 5010 Pics - 11 Aug 22















