



Idaho Division of Aeronautics

5010 AIRPORT INSPECTION FORM/REPORT



SLOPE RATIO CALCs: D=200/HT (PAVED) ** D/HT (UNPAVED) ** H=D/S ** D=SxHT ** HT=height D=Dist S=Slope Ratings: Excellent=E Good=G Fair=F Poor=P Failed=FD

Airport: SODA SPRINGS LocID: U78 (Paved) Undevelopd NPIAS: Y (N) INSP Date: 10 Jun 21

Rwy 1: 13-31 Pub Dims: 2500' L x 50' W G-Earth Dims: L x W FAA Dims: L x W Actual Dims: 2545' L x 51' W Measured: (Y) N VEH DME + WHEEL Rwy Markings: NONE Rwy Lights: Y (N) Veg Ctrl: FAIR SFC Type: ASPHALT SFC Cond: POOR Rwy End: 13 Lat N: 42° 39' 5.91" Long W: 111° 34' 59.04" Elev 1 GPS: 5843' Elev 2 WCP: 5828' ± 8' Hdg 1: 134° / 314° Hdg 2: 135° / 315° Ctlg Obstn: (Y) N Description: 45' PWR. POLE @ 450', 50'L Close-in Obstn: (Y) N Description: Rwy End: 31 Lat N: 42° 38' 45.10" Long W: 111° 34' 41.35" Elev 1 GPS: 5851' Elev 2 WCP: 5851' ± 6' Hdg 1: 314° / 134° Hdg 2: 315° / 135° Ctlg Obstn: (Y) N Description: 40' PWR LINE @ 600' ON CL. Close-in Obstn: (Y) N Description:

Remarks: BMs = Boundary Markers // CL= Center line // THIS RWY IS NOT V. WELL KEPT; IT'S IN POOR CONDITION, HAS NO MARKINGS & NO LIGHTS. PAVT HAS LOTS OF CRACKS W/ GRASS GROWING THROUGH; NEEDS NEW PAVT.

Rwy 2: 16-34 Pub Dims: 3900' L x 50' W G-Earth Dims: L x W FAA Dims: L x W Actual Dims: 3940' L x 50' W Measured: (Y) N VEH DME + WHEEL Rwy Markings: #s+CL Rwy Lights: (Y) N Veg Ctrl: FAIR SFC Type: ASPHALT SFC Cond: POOR Rwy End: 16 Lat N: 42° 39' 8.22" Long W: 111° 35' 0.28" Elev 1 GPS: 5828' ± 5' Elev 2 WCP: 5830' ± 6' Hdg 1: 159° / 339° Hdg 2: 158° / 338° Ctlg Obstn: (Y) N Description: 17' RD @ 200', 100' R Close-in Obstn: (Y) N Description: Rwy End: 34 Lat N: 42° 38' 35.27" Long W: Elev 1 GPS: 5847' Elev 2 WCP: 5850' Hdg 1: 340° / 160° Hdg 2: 339° / 159° Ctlg Obstn: Y (N) Description: Close-in Obstn: Y (N) Description:

Remarks: THIS IS THE RWY THAT GETS USED THE MOST & IT NEEDS LOTS OF TLC. SFC PAVT IS IN DIRE NEEDS OF REPAIRS AS SFC IS PLEGGED BY LOTS & LOTS OF CRACKS - SOME OLD & TREATED & SOME NEW & UNTREATED; NEW PAVT WOULD BE NICE.

Taxiway: Y N Sfc Type: Sfc Cond: Markings: Y N Signs: Y N Cond: Lights: Y N Reflectors: Y N Both Veg Ctrl: Remarks: RWY 16 HAS A 305' DIRT TRESHOLD. RWY LIGHTS MOSTLY BROKEN; UNABLE TO

Ramp/TieDown Area Sfc Type: ASPHALT Sfc Cond: POOR # of Spots: 4 # w/Chains/TDs: 0 VEH/RY Markings: Y (N) Lights: N/A Signs: Y (N) Veg Ctrl: GOOD FUNCTIONALITY Remarks: RAMP AREA IS ALSO IN ROUGH SHAPE - HAS AREAS OF MISSING ASPHALT W/ LOOSE GVL IN FRONT OF PILOT'S LOUNGE. OF WHAT IS LEFT.

Windsock(s) # of WS on AFLD: 3 WS1 Cond: FAIR Lights: Y (N) Loc: BY THE FUEL PUMP WS2 Cond: GOOD Lights: (Y) N Loc: BETWEEN RWYS 13 & 16 WS3 Cond: GOOD Lights: Y (N) Loc: CLOSE TO RE 34 Std 1 Type: WOOD Cond: FAIR Painted: Y (N) Color Seg Cr: Y (N) Type: TP: Y N Std 2 Type: METAL Cond: GOOD Painted: (Y) N Color WHITE Seg Cr: (Y) N Type: TP: Y N Std 3 Type: METAL Cond: GOOD Painted: Y N Color Seg Cr: Y (N) Type: TP: Y N Remarks: # 2 WS HAS A SEGMENTED CIRCLE MADE OF 556 ARMS CUT IN HALF & PAINTED - ALTERNATING WHITE / ORANGE COLORS. WEEDS GROWING INSIDE

Boundary Markers Cond: Veg Ctrl: Type: Metal Wood Rocks Other N/A Painted: Y N Remarks: Misc/Other Rot BCN: Y (N) Type: HT: THE SEG. Circle. Cond: Working: Y N ? Verif: H/N/verif Verif N/A Circle. Veg Ctrl: Signs: Y N Remarks:

Allen Tygert/Soda Springs Airport Pictures - 10 Jun 2021

